### REPLACEMENT SHEET






FIG. 1 (Prior Art)




FIG. 2 (Prior Art)





FIG. 3






FIG. 5A




FIG. 5B




FIG. 5C

### REPLACEMENT SHEET




FIG. 5D




FIG. 5E




FIG. 5F





FIG. 6



### REPLACEMENT SHEET

## 7/27







FIG. 8


### REPLACEMENT SHEET



### REPLACEMENT SHEET







**FIG. 12A** 




FIG. 12B

### REPLACEMENT SHEET




FIG. 12C








FIG. 13














### REPLACEMENT SHEET






FIG. 19

### REPLACEMENT SHEET

### 19/27

# 162-**MOSCAP Tunneling Junction**




FIG. 20

# 164pFET Tunneling Junction




FIG. 21

### REPLACEMENT SHEET





FIG. 22






FIG. 24






FIG. 25



SERIAL NO.: 10/814,868 OUR REFERENCE NO.: IMPJ-0027C (033327-066)

### REPLACEMENT SHEET



## 26/27




FIG. 28

# DAVID B. RITCHIE THELEN REID BROWN RAYSMAN & STEINER LLP SERIAL NO.: 10/814.868

OUR REFERENCE NO.: IMPJ-0027C (033327-066)

#### REPLACEMENT SHEET




FIG. 29A




FIG. 29B